

## Winterizing a Salt Chlorine Generator:

- Disconnect the union that goes directly into the salt cell manifold. (If the filtration system is a Sta-Rite System: 3 Modular Media Filter, undo the lowest union on the filter.)
- Force air into the manifold using a shop-vac or air compressor, blowing water through the pipes back into the pool.
- Remove the salt cell on the manifold to make sure all the water is out. Concentrate on getting all the water of the spring check valve on the bottom of the manifold. You can vacuum out the water with a shop-vac if need be.

## Leave unions loose at the filter.

